

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073

Photo #: 1
Risk



Photo #: 2
Stairwell to steeple
damaged

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo # 3: Note falling ladders. These chase ladders led to steeple peak



Photo #4: Fallen timber construction in stairwell leading steeple

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:5 Fallen timber construction



Photo # 6 Fallen timber construction

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:7 Looking up from steeple access to where steeple existed prior



Photo # 8 Fallen stairwell in Steeple access

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073

Photo #:9 Building access restricted




Photo # 10 Overview of interior under renovation



Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:11 Photo taken of picture of steeple as it existed prior to storm. Note the long arches leading to the steeple.



Photo # 12 Ornate woodwork on steeple

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073

Photo #:13 Ornat
ewoodwork on steeple



Photo # 14 Decorative
wood columns on steeple



Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:15 Decorative wood columns on steeple



Photo # 16 Full panels of Slate roofing and sheathing from steeple

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:17 Debris from Steeple



Photo # 18 view of area where steeple stood

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073

Photo #:19 Overview of area
where steeple previously
stood



Photo # 20 Note decorative
woodwork similar to that on
the arches of the
promenade

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:21 Overview of existing slate roof with some blown tiles



Photo # 22 Tree Felled by wind

Photo Mounting Sheet



Insured: United Universalist
Date Taken: 06/07/2011

Claim Number: 11013760
Our File Number: 1860073



Photo #:23 Salvaged slate roof tiles



Photo # 24 Area blow steeple with stress cracks in block construction